

STATE OF CONNECTICUT DEPARTMENT OF ENVIRONMENTAL PROTECTION



February 24, 1986

Mr. John Whitehead Pratt and Whitney Aircraft 400 Main Street East Hartford, Connecticut 06108

Re: Incinerator Closure, East Hartford

Dear Mr. Whitehead:

RCRA RECORDS CENTER
FACILITY Protts Whitney-Main St
1.D. NO.CTD990672081
FILE LOC. R-1B
OTHER RDMS \$ 2740

The closure plan for the Pratt and Whitney, East Hartford incinerator dated January 10, 1986 has been reviewed by the Department of Environmental Protection. In order to make the closure plan complete, the following information is required:

- 1. State what hazardous solvents will be tested for and their concentration level for hazardous waste determinations.
- 2. In the decontamination procedure include the waste feed lines and incinerator nozzles.
- 3. How will the incinerator be determined to be clean? Conduct a "wipe test" or by some similar means verify equipment to be hazardous waste free. In order to conduct a wipe test, the charging systems, combustion chamber, and pollution control devices may be wiped with a clean cellulose pad to extract contaminants then analyzed for hazardous constituents of concern.

The closure plan stated that once the incinerator equipment is removed, CWTP activities will be conducted in this area. If CWTP activities are hazardous waste activities, this procedure may constitute a facility modification and as such must comply with S270.72 of 40 CFR.

Upon receipt of a complete closure plan, the plan will be public noticed.

If there are any questions, call 566-2264.

Sincerely

George Dews

Senier Sanitary Engineer

Hazardous Waste Management Section

GD:et

cc: A. Hoffman - U.S. EPA Kevin Vidmar -P&W_

Phone: